

## 9. COAL SUPPLY

List of critical Thermal Power Stations having critical coal stock of less than 7 days

(As on 31-07-08)

### NORTHERN

1	I.P. Station	Due to less receipt of coal during the month of July 2008 i.e. 54% of the linkage.
2	Badarpur	Stock has depleted due to less receipt of coal during the month of July 2008 i.e. 74% of the linkage.
3	Panipat	Due to less receipt of coal during the month of July 2008 i.e.63% of the linkage.
4	Lehra Mohabbat	Due to less receipt of coal during the month of July 2008 i.e. 58% of the linkage.
5	Anpara	Stock has depleted due to less receipt of coal during the month of July 2008 i.e. 88% of the linkage.
6	Dadri	Due to less receipt of coal during the month of July 2008 i.e. 81% of the linkage.
7	Rihand STPS	Due to less receipt of coal during the month of July 2008 i.e. 96% of the linkage.
8	Singrauli STPS	Due to less receipt of coal during the month of July 2008 i.e. 90% of the linkage.
9	Tanda	Due to less receipt of coal during the month of July 2008 i.e. 78% of the linkage.
10	Unchahar	Due to less receipt of coal during the month of July 2008 i.e. 73% of the linkage.

### WESTERN

11	Sanjay Gandhi	Due to less receipt of coal during the month of July 2008 i.e. 75% of the linkage.
12	Vindhyachal STPS	Due to less receipt of coal during the month of July 2008 i.e. 93% of the linkage.
13	Bhusawal	Due to higher generation and in adequate linkage.
14	Chandrapur	Stock could not be built up due to unloading limitation.
15	Khaperkheda II	Due to less receipt of coal during the month of July 2008 i.e. 97% of the linkage.
16	Dahanu	Due to less receipt of coal during the month of July 2008 i.e. 74% of the linkage.

### SOUTHERN

17	Dr. N.Tata Rao	Due to higher generation and in adequate linkage.
18	Kothagundam	Low linkage and higher generation result in higher consumption of coal during the month of July 2008.
19	Rayalseema	Due to less receipt of coal during the month of July 2008 i.e. 97% of the linkage.
20	Ramagundam STPS	Due to less receipt of coal during the month of July 2008 i.e. 84% of the linkage.
21	Simhadri	Low linkage and higher generation result in higher consumption of coal during the month of July 2008.
22	Raichur	Due to less receipt of coal during the month of July 2008 i.e. 56% of the linkage.
23	Ennore	Due to less receipt of coal during the month of July 2008 i.e. 71% of the linkage.
24	Tuticorin	Due to less receipt of coal during the month of July 2008 i.e. 64% of the linkage.

### EASTERN

25	Kahalgaon	Coal supplies through MGR has been restricted due to poor performance of Rajmahal CHP. Most of the time 2 out of 4 crushers are not operation causing the ground bunker to empty. Coal supply to this station has also been hit by frequent law and order problems. In July 2008 receipt is only 52% of the linkage.
26	Ib Valley	Due to less receipt of coal during the month of July 2008 i.e. 77% of the linkage.
27	Talcher STPS	Due to less receipt of coal during the month of July 2008 i.e. 85% of the linkage.
28	Patratu	Stock depleted due to less receipt of coal during the month of July 2008 i.e. 76% of the linkage.
29	Tenughat	Due to less receipt of coal during the month of July 2008 i.e. 23% of the linkage.
30	Durgapur	Due to unloading constraints.
31	Mejia	Unloading constraint due to delay in commissioning of the second stream of Track Hopper. The same is now expected by September 2008 end.
32	Bakreshvar	Due to less receipt of coal during the month of July 2008 i.e. 61% of the linkage.
33	Bandel	Due to less receipt of coal during the month of July 2008 i.e. 59% of the linkage.
34	Kolaghat	Due to less receipt of coal during the month of July 2008 i.e. 61% of the linkage.
35	Santalidih	Due to less receipt of coal during the month of July 2008 i.e. 30% of the linkage.
36	New Cossipore	Due to less receipt of coal during the month of July 2008 i.e. 78% of the linkage.
37	Titagarh	Due to less receipt of coal during the month of July 2008 i.e. 75% of the linkage.
38	Farakka	Coal supplies through MGR has been restricted due to poor performance of Rajmahal CHP. Most of the time 2 out of 4 crushers are not operational, causing the ground bunker to empty. Coal supply to this station has also been hit by frequent law and order problems. In July 2008 receipt is only 77% of the linkage.

Note: Number of Power Stations having critical coal stock at the end of previous month =38